



GARY R. HERBERT  
Governor  
SPENCER J. COX  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

## Minerals Inspection Report

Report Date: 07/09/2014

Reviewed

*JB*

Mine Name: Devil's Slide Quarry	Permit Number: M/029/0001	Mine Status: Active
Operator Name: Holcim (US) Inc.	Inspection Date: 07/31/2013	Permit Fees: Paid
Inspector(s): L. Heppler	Inspection Time: 8:00 AM	Bond Amount: \$5,000,000
Attendee(s): Ken George	Weather: Sunny, Dry	Bond Escalation: 08/30/2012
Inspection Purpose: Routine annual inspection		Prior Inspection: 11/30/2010

### Conclusions and Recommendations

The Operator needs to complete Notice of Intention. OGM to continue annual inspections and monitor the site when in the area.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i> Operator is current with permit fees. Bond escalation is past due as shown above.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i> Project is gated, highwall is significant, there is no underground workings on the site.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. <i>Protection of Drainages/Erosion Control</i> No erosional problems noted, sediment pond adjacent to the Weber river has had problems in the past - see attached photo	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. <i>Deleterious Material</i> Fuel storage is adequate.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. <i>Roads (maintenance, surfacing, dust control, safety)</i> Roads were maintained and in good condition, water was used for dust suppression.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. <i>Reclamation</i> No concurrent reclamation was noted at the time of inspection. Future reclamation site is notes - see attached photo	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i> No regrading at the site at the time of inspection.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. <i>Soils</i> Site has several small soil stockpiles, but not enough volume for the entire mine site at final reclamation.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. <i>Revegetation</i> No site revegetation has been started.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. <i>Other</i> This line is intentionally left blank.	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature:

CC: Brent Sumsion - Geneva Rock Product

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M029-Morgan/M0290001-DevilsSlide/inspections/TNSP-07312013.pdf







Main pit and highwall



Sediment pond adjacent to Weber River



Area slated for concurrent reclamation



Haul road from mine to process area